



Photo No. 1

Sandblast formliner used in concrete pylon on Replacement of Somerset County Bridge F0808 located in Somerville, NJ



17TH STREET BRIDGE REHABILITATION
CITY OF OCEAN CITY,
CAPE MAY COUNTY, NEW JERSEY

SCALE:

N.T.S.

DATE:

October 2012

JOB No.

5805.001

PHOTO No.

1



Photo No. 2

Black metal railing used on Monmouth County Bridge W-33 Replacement
located in Belmar, NJ



17TH STREET BRIDGE REHABILITATION
CITY OF OCEAN CITY,
CAPE MAY COUNTY, NEW JERSEY

SCALE:

N.T.S.

DATE:

October 2012

JOB No.

5805.001

PHOTO No.

2



Photo No. 3

Black metal railing used on Monmouth County Bridge W-33 Replacement
located in Belmar, NJ



17TH STREET BRIDGE REHABILITATION
CITY OF OCEAN CITY,
CAPE MAY COUNTY, NEW JERSEY

SCALE:

N.T.S.

DATE:

October 2012

JOB No.

5805.001

PHOTO No.

3